




Controller and Inputs



3.3 V Buck Converter



Motor Driver



12 V Input

